

Hamilton Beach® Commercial Food Blender Repair Kit



Model #98500

- With complete cutting assembly, clutch, gasket, and retainer nut
- For model HBF500